

JOSEPH P. BILECKI
LAND SURVEYOR

221 Matty Ave.

Phone 455-1169

August 28, 1970

Subject: Sanitary Fill Area in Town of Salina

Location: Bounded - North by Ley Creek South by Penn Central RR.
East by Route #11 West by Crouse Hinds Property

Elevations: *East*

- 1 - Center line pavement 7th North St.
Center line entrance road to fill area
Assumed elevation - 100.0
- 2 - Ley Creek station 18/ 00
Top covered fill - 101.0
- 3 - Covered fill south of entrance road
north of wood power pole line - 104.8
- 4 - Uncovered fill north of entrance road
south of Ley Creek - 106.8
- 5 - Uncovered fill north of Penn Central RR.
south of wood power pole line 103.8
- 6 - Uncovered fill - area in operation - east end of
sanitary fill area nearest Route #11
107.3
- 7 - Center line pavement Route #11 - opposite end of
east wing wall RR bridge 104.84

Elevations at 2-3-4-5 in area lying about midway between 7th North St.
and Route #11

Observations - No evidence of sand bank fill along Ley Creek or established
bench marks to control elevations.

Joseph P. Bilecki - L. S. 31722

/s/ Joseph P. Bilecki

JOSEPH P. BILECKI
LAND SURVEYOR

221 Matty Ave.

Phone 455-1169

August 28, 1970

Subject: Sanitary Fill Area in Town of Salina

Location: Bounded - North by Ley Creek South by Penn Central RR.
East by Route #11 West by Crouse Hinds Property

Elevations:

- 1 - Center line pavement 7th North St.
Center line entrance road to fill area
Assumed elevation - 100.0
- 2 - Ley Creek station 18/ 00
Top covered fill - 101.0
- 3 - Covered fill south of entrance road
north of wood power pole line - 104.8
- 4 - Uncovered fill north of entrance road
south of Ley Creek - 106.8
- 5 - Uncovered fill north of Penn Central RR.
south of wood power pole line 103.8
- 6 - Uncovered fill - area in operation - east end of
sanitary fill area nearest Route #11
107.3
- 7 - Center line pavement Route #11 - opposite end of
east wing wall RR bridge 104.84

Elevations at 2-3-4-5 in area lying about midway between 7th North St.
and Route #11

Observations - No evidence of sand bank fill along Ley Creek or established
bench marks to control elevations.

Joseph P. Bilecki - L. S. 31722

/s/ Joseph P. Bilecki